

# Imray Correction Notice

16 May 2012

IC2100.5-1

## Chart 2100+5 WGS 84

*Edition May 2010*

*Date of printing May 2010*

The following corrections should be noted:

### 1 Out Ruytingen

Insert *AIS* at **Ruytingen SW** Fl(3)G.12s Lt buoy in 51°05'·02N 1°46'·74E (ILNW 240/10)

### 2 Deal northeastwards, Gull Stream

Move Lt buoys:

**N Goodwin** to 51°18'·12N 1°30'·35E

**NW Goodwin** to 51°16'·73N 1°28'·60E

**Goodwin Fork** to 51°14'·38N 1°26'·70E (ILNW 530/10)

### 3 Ramsgate (Inset)

Insert *Igd Works in progress (2011)* centred on 51°19'·62N 1°24'·91E (ILNW 112/11)

### 4 Goodwin Sands westwards, Gull Stream

Delete Bell at **NW Goodwin** Lt buoy in 51°16'·73N 1°28'·60E (ILNW 157/11)

### 5 Sandettié Bank southwestwards

Amend Lt at **Sandettié** LtV to Fl.5s12m15M and add *Igd AIS* in 51°09'·35N 01°47'·12E (ILNW 57/12)

### 6 Gore Channel westwards

Move **E Last** Q.R Lt buoy to 51°23'·63N 01°12'·56E and rename **Reculver**.

Delete **Hook Spit** Q.G Lt buoy in 51°24'·07N 01°12'·21E (new position off chart). (ILNW 58/12)

### 7 Richborough Port

Delete:

**CHY**(135) in 51°18'·61N 1°20'·78E

**3 COOLING TOWERS** (103) and assoc. syms close N, NW + W. (ILNW 182/12)